

**NEW HOUSE – THANKFULLY FAR FROM USUAL!**

**Developer ‘ran out’ of PVC fascia board!**



**Same new house. National builder had constructed air bricks adjacent to ground level.**



**Beads of condensation and damp trusses to modern 2 year old house resulting in – see below – normally condensation is caused by occupiers.**



**The ceiling glass fibre wool heat insulation was almost saturated.**

