

NEW HOUSE – THANKFULLY FAR FROM USUAL!

Developer ‘ran out’ of PVC fascia board!



Same new house. National builder had constructed air bricks adjacent to ground level.



Beads of condensation and damp trusses to modern 2 year old house resulting in – see below – normally condensation is caused by occupiers.



The ceiling glass fibre wool heat insulation was almost saturated.

